

Wasco County Landfill

Site Safety Rules - Trucks



- HOT ZONE SAFETY - Communicate with Wasco County Landfill employees at all times while on site
 - "All Stop" – A Wasco County Landfill employee may call an "all stop" at any time. If you hear the "all stop" you must completely stop your vehicle. Do not move until you hear the "all clear"
- Speed Limit – 15 MPH
- CB radios required while on site
 - Radios are to be used strictly for Landfill operations communication
- Follow all site signage rules
- Safety vests are to be worn on site at ALL times
- No Scavenging
- No Smoking
- No cell phone usage onsite
- Activities must be done in these designated areas only:
 - Cleanout
 - Tarping/Untarping/Undoing locks – DO NOT climb on trailers. Call site personnel for assistance
 - Commercial dump – Must dump AT LEAST 50 feet away from other vehicles
 - End dump – Must dump AT LEAST 50 feet away from other vehicles
 - Public dump
 - Asbestos
 - Liquid disposal
- Do not exit vehicle in the active area